To:USPTO

RECEIVED CENTRAL FAX CENTER JUL 2 7 2006

IN THE SPECIFICATION

After the third paragraph on page 7, please add a new paragraph:

As seen in Figure 6E and 6F, the flipper arms 36 drop back down after passing the cam
48 to retract the tip of the second segments 40 below the top surfaces of the conveyor chain loops
12.